


**XR6, XR10, XR20, and XR40 Update**

**November 19, 1998**

**\* \* \* \* IMPORTANT INFORMATION \* \* \* \***


The end-of-line resistor for zone 9 must not be accidentally connected to the positive terminal of zone 10 as shown below.

**INCORRECT**



When zone 9 is incorrectly connected to zone 10, a false alarm may occur on zone 2 of the panel when the panel picks up the telephone line to communicate to the receiver.

**CORRECT**



**\* \* \* \* IMPORTANT INFORMATION \* \* \* \***

